



Project: St Mary's Church, Portreath

Client: St Mary's Church Committee

Concrete Repairs

Main Contractor: SWCR Ltd

Date: June 2016



The Problem

Several of the window surround have various degrees of cracking, spalling and bulging areas. Some of the windows also had rust staining and exposed corroded reinforcement. Several quite large lumps of the concrete had completely de-bonded and have started to fall off, causing a serious safety risk to church users below.



The Solution

All the defective areas were broken out and all loose concrete were removed. All exposed reinforced steel was then cleaned and coated with Flexcrete Steel Reinforcement Protector 841 and Flexcrete Bonding Bridge 842. The treated areas were then repairs with a Flexcrete Monomix Concrete Repair mortar and a final re profiling and levelling coat of Flexcrete Monolevel 844 SP applied.



© South West Concrete Repairs Ltd | Registered in England & Wales No. 3431115

Unit 17, Reynolds Park
8 Bell Close
Newnham Industrial Estate
Plymouth
PL7 4FE

E sales@swconcreterepairs.co.uk
W www.swconcreterepairs.co.uk
T 01752 561300
F 01752 605900