

# St Margaret Mary's Church, Plymstock



**Project:** St Margaret Mary's Church, Plymstock

**Client:** Diocese of Plymouth Main Contractor: SWCR Ltd

Date: October 2016



## The Problem

We were contacted by, Diocese of Plymouth, to have a look at the entrance canopy to St Margaret Mary's Church in Plymstock, Plymouth. The canopy had various areas of spalling which have occurred due to the Asphalt Roofing leaking over a period of time.







# The Solution

Due to the ingress of water from the leaking roof, the asphalt and mineral felt coatings needed to be removed, the deck power washed to remove any contaminates and debris. Then once dry a fluid applied roof coating of Decothane SP was applied to the roof. This 3 coat system incorporates the use of a Reemat Premium Glass Fibre Reinforcement matting and gives a fully seamless roof coating when completed. Once satisfied that the leaking had stopped, the spalled areas were repaired. These areas were broken out, the steel reinforcement cleaned and treated to preserve and then repaired with a repair mortar. Once all repairs were completed and cured a levelling mortar, Monolevel 844SP was applied, this then gives an additional layer of protection to the underside of the canopy.

## © South West Concrete Repairs Ltd | Registered in England & Wales No. 3431115

Unit 17, Reynolds Park 8 Bell Close Newnham Industrial Estate Plymouth PL7 4FE

sales@swconcreterepairs.co.uk www.swconcreterepairs.co.uk

01752 561300 Т

Е

W

01752 605900