

**Project:** Milford Schools, Yeovil

**Client:** Somerset County Council

Concrete Repairs

**Main Contractor:** D R Jones

**Date:** July - August 2018



### *The Problem*

We were contacted by Somerset County Council to have a look at the primary and infant school. The concrete elements (window surrounds, columns, cills etc) throughout both schools had cracking and spalling of surface concrete, with some areas of exposed reinforcement bars.



### *The Solution*

Each elevation was visually checked for defects and hammer tested. Once all of the defects were identified they were broken out and all loose debris was removed. Once broken out all of the steel reinforcement was cleaned and treated with a steel primer. Each defective area was then shuttered and repaired.

Products used: Intercrete 4800 (Monomix), Intercrete 4871 (Steel Reinforcement Protector 841), Intercrete 4812 (Bonding Bridge)

© South West Concrete Repairs Ltd | Registered in England & Wales No. 3431115

Unit 17, Reynolds Park  
8 Bell Close  
Newnham Industrial Estate  
Plymouth  
PL7 4FE

**E** sales@swconcreterepairs.co.uk  
**W** www.swconcreterepairs.co.uk  
**T** 01752 561300  
**F** 01752 605900